



# CODE ENFORCEMENT BOARD HEARING AGENDA

MARCH 22, 2016 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

# CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

**Note:** If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

**Board Members:** • Chad Thilborger, **Chair** • Paul Dooley, **Vice Chair** • Joan Hinton

- Lakhi Mohnani Patrick McGee Joshua Miron (alternate) Robert Smith (alternate)
- Michael Madfis (alternate) **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

-----

#### HEARING SCHEDULED

\_\_\_\_\_\_

CASE NO: CE14080194 CASE ADDR: 5111 NE 18 AV

OWNER: INTERNATIONAL INVESTMENT PARTNERS L

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE INSTALLATION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE14090494
CASE ADDR: 1205 NE 3 AV
OWNER: BLAKE, HEATHER
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. BATHROOM REMODEL.

-----

CASE NO: CE14110753 CASE ADDR: 808 NW 9 AVE

OWNER: SCULLY, JOSEPH L & LINDA

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 111.1.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. SECOND FLOOR STORAGE IS BEING USED AS OFFICE

SPACE.

\_\_\_\_\_\_

CASE NO: CE15040769

CASE ADDR: 409 N VICTORIA PARK RD

OWNER: STEWART, SCOTT

HABAYEB, ZIAD

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PERGOLA BUILT ON THE FRONT OF THE PROPERTY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15071410 CASE ADDR: 2427 NE 8 ST

OWNER: JAMES, GORDON D & JUSTINE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CARPORT WAS ENCLOSED AND CONVERTED INTO A GARAGE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

-----

CASE NO: CE15072274
CASE ADDR: 107 NE 17 AVE

OWNER: PROMOTRADE USA INC INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. FRONT YARD LANDCAPE WAS MODIFIED AND GRAVEL WAS INSTALLED ON THE SWALE AREA.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15072497

CASE ADDR: 4020 GALT OCEAN DR OWNER: OCEAN CLUB CONDO ASSOC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. REMOVAL OF PLANTER AND ADDITION OF PARKING

SPACES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15080173 CASE ADDR: 2070 NW 29 AVE OWNER: RHA 2 LLC

INSPECTOR: ALEJANDRO DELRIO VIOLATIONS: FBC(2014) 105.1

> THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

> > BUT NOT LIMITED TO:

1. HURRICANE SHUTTERS INSTALLATION.

2. NEW CENTRAL AIR CONDITIONING SYSTEM WITH DUCTS.

3. ELECTRICAL CONNECTION FOR AIR CONDITIONING SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15090113 CASE ADDR: 424 NW 21 TER

OWNER: PRESCOTT, RAYMOND B II

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. EXTERIOR WINDOWS REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15091538
CASE ADDR: 4840 NW 9 TER

OWNER: DEGARCIA, VICTORIA M &

DUARTE, GERMAN

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. SHINGLE REROOF.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

-----

CASE NO: CE15092237 CASE ADDR: 1005 SW 15 TER

OWNER: VAN WOERDEN, SHANNON INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CENTRAL AIR CONDITIONER CHANGE OUT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15092395 CASE ADDR: 1213 NW 19 CT

OWNER: GAINES, JOHNNIE EST INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. REPLACEMENT OF SEVERAL WINDOWS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15101205 CASE ADDR: 1150 NW 18 AV OWNER: BROWN, ANNIKO INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE INSTALLATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE14121223 CASE ADDR: 4 S GORDON RD

OWNER: 4 S GORDON RD LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS

CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A/C SYSTEM.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14080603

CASE ADDR: 358 CITY VIEW DR
OWNER: ANDERSON, ERIN E

BLACK, BENJAMIN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. THE OWNER HAS INSTALLED A SHED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14121561
CASE ADDR: 3801 SW 12 PL
OWNER: FRANCOIS, RONALD

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODELING KITCHENS AND BATHROOMS.

FBC(2010) 105.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE PERMIT HAS BEEN VOIDED THEREFORE THE NEW FENCE BECOMES WORK WITHOUT PERMIT.

FBC(2010) 105.4.4

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE INSTALLATION OF NEW PLUMBING FIXTURES.

#### FBC(2010) 105.4.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL WORK HAS BEEN PERFORMED AND THE PERMIT HAS EXPIRED THEREFORE BECOMING WORK WITHOUT PERMIT.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE15010368
CASE ADDR: 3811 SW 12 PL
OWNER: DAGUINDEAU, LOUIS

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODELING KITCHENS AND BATHS.

#### FBC(2010) 105.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS HAVE BEEN INSTALLED.

#### FBC(2010) 105.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE HAS BEEN INSTALLED.

### FBC(2010) 105.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. KITCHENS AND BATHS.

FBC(2010) 105.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. NEW ELECTRICAL FIXTURES, OUTLETS AND SWITCHES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15051252 CASE ADDR: 2299 SW 28 TER

OWNER: WOODS, RYAN PATRICK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLED WOOD AND CHAIN LINK FENCE WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

THE TERRITOR TROOPER.

------

CASE NO: CE15061039 CASE ADDR: 1020 NW 4 AV

OWNER: PIERRE, JOSEPH EDNY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. BUILT WOOD FENCE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16010842
CASE ADDR: 2312 NW 14 ST
OWNER: PERSAUD, OMCHAND

INSPECTOR: JOSE ABIN

VIOLATIONS: 9-259

WATER DAMAGE FROM LEAKING ROOF HAS MADE THE RESIDENCE UNINHABITABLE. CEILING HAS FALLEN EXPOSING RAFTERS.

#### FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BUILT A SECOND BATHROOM.
- 2. BUILT CHASES TO CONCEAL DUCT WORK

#### PERMITS REQUIRED:

- 1. BUILDING
- 2. ELECTRICAL
- 3. MECHANICAL
- 4. PLUMBING

# FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO: BATHROOM ADDITION:

- 1. ADDED TOILET.
- 2. ADDED VANITY SINK.
- 3. ADDED SHOWER WITH PAN.

### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES,

OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SYSTEM HAS BEEN ALTERED AND THE WIRING MODIFIED. FLIPPING ALL THE BREAKERS TO THE OFF POSITION DOES NOT DISCONNECT THE POWER TO ALL FIXTURES AND OUTLETS.

# FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. CENTRAL A/C SYSTEM
- 1. NEW CONDENSOR UNIT. MANUFACTURE DATE 08/2015.
- 2. NEW EVAPORATOR UNIT. MANUFACTURE DATE 08/2015.
- 3. ADDED EXHAUST VENT IN BATHROOM ADDTION.

#### FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS ISSUED AFTER WORK HAS COMMENCED, AFTER THE FACT, TO BE DOUBLE FEE.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2014) 116.2.1.2.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL SYSTEM HAS BEEN ALTERED AND THE WIRING MODIFIED. FLIPPING ALL THE BREAKERS TO THE OFF POSITION DOES NOT DISCONNECT THE POWER TO ALL FIXTURES AND OUTLETS.
  - A LETTER FROM A CERTIFIED AND LICENSED ELECTRICIAN IS REQUIRED TO DEEM THE STRUCTURE SAFE FOR OCCUPANCY.

NEC(2005) 110.27

BREAKER PANEL HAS MISSING BLANKS AND LIVE PARTS ARE EXPOSED.

NEC(2005) 440.22(C)

THE POWER SUPPLY AND THE A/C UNIT ARE NOT COMPATIBLE TO MANUFACTURERS SPECIFICATIONS AND CAUSES THE CIRCUITS TO OVERHEAT AND GIVE OFF A BURNING ODOR.

\_\_\_\_\_\_

CASE NO: CE15100767
CASE ADDR: 1029 NW 1 AV
OWNER: ANGELS TJ LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURE WAS BUILT AT THE FRONT ENTRY.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_

CASE NO: CE15101181
CASE ADDR: 408 NE 8 AV

OWNER: EWING, RANDALL JR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT WOOD DECK AT BACKYARD.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15101425

CASE ADDR: 640 TENNIS CLUB DR # 308

OWNER: RUBINSTEIN, GARY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS.
- 2. REMOVAL OF KITCHEN CABINETS AND ALTERATION OF SOFFITS AND CEILING.

#### FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING

TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

1. DUCT WORK HAS BEEN MODIFIED.

#### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

1. SINK HAS BEEN REMOVED AND THE PLUMBING SYSTEM HAS BEEN MODIFIED.

### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

1. OUTLETS AND FIXTURES HAVE BEEN REMOVED AND THE ELECTRICAL SYSTEM MODIFIED.

# FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

### FBC (2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS, A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF UP TO \$500 PER DAY PER VIOLATION UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

\_\_\_\_\_\_

CASE NO: CE15101515 CASE ADDR: 1107 NW 11 ST

OWNER: STARK EQUITY GROUP LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING.
- 2. DRYWALL HAS BEEN INSTALLED.
- 3. BEARING WALLS ARE BEING ALTERED.
- 4. NON-BEARING WALLS HAVE BEEN ALTERED.
- 5. PARTITIONS HAVE BEEN MOVED.
- 6. INTERIOR FLOOR PLAN CONFIGURATION HAS BEEN ALTERED.

### FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR DEMOLITION OF NON-BEARING WALLS.
- 2. INTERIOR DEMOLITION OF BEARING WALLS.
- 3. DRYWALL HAS BEEN REMOVED AND REPLACED.

#### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WATER SPIGOTS ON EXTERIOR OF DWELLING HAVE BEEN REPLACED.
- 2. NEW WASTE LINES AND CLEANOUTS HAVE BEEN INSTALLED.
- 3. NEW WATER SUPPLY LINES IN LAUNDRY ROOM, KITCHEN AND BATHROOMS.
- 4. PLUMBING FIXTURES ARE BEING REPLACED IN KITCHEN, BATHROOMS AND LAUNDRY ROOMS.

#### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CIRCUITS IN BREAKER PANEL ARE BEING MODIFIED.
- 2. NEW CIRCUITS ARE BEING INSTALLED IN KITCHENS, BATHROOM, LAUNDRY ROOM AND OTHER LIVING AREAS.

- 3. NEW FIXTURES ARE BEING INSTALLED IN KITCHENS, BATHROOM, LAUNDRY ROOM AND OTHER LIVING AREAS.
- 4. SWITCHES AND OUTLETS ARE BEING REPLACED AND MODIFIED.

### FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF UP TO \$500 PER DAY PER VIOLATION UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

\_\_\_\_\_\_

CASE NO: CE15101560
CASE ADDR: 3121 SW 20 CT
OWNER: BARNETTE, KYLE W

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEMOLITION OF ROOF.

#### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION NOT LIMITED TO:

1. WATER HEATER MANUFACTURED IN JANUARY 2010 INSTALLED.

#### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. ELECTRICAL FOR WATER HEATER.

#### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE15090546
CASE ADDR: 1829 SW 11 ST
OWNER: LANIGAN, THOMAS P

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOM ALTERATIONS TO THE WALL STRUCTURE REOUIRING PERMIT.

### FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. GARAGE DOOR INSTALLATION REQUIRING A PERMIT.

#### FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES REQUIRING A PERMIT.

# FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS NOT LIMITED TO:

1. CHANGEOUT OF ELECTRICAL FIXTURES REQUIRING PERMIT.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE15091995 CASE ADDR: 516 NW 1 AVE

OWNER: 516 LLC

%CAROL D LENAHAN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP S-1 TO AN ASSEMBLY GOUP A-5 WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

### FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE'S GATE WERE ALTERED BY THE INSTALLATION OF A 12FT HIGH WOOD GATE ALSO WOOD PALLETS WERE HANG IN THE CH/LNK FENCE 12 FEET ON THE AIR, AND THEY CAN BE UPLIFTED BY TROPICAL STORM WINDS.

### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. ELECTRICAL MODIFICATIONS IN STAGE AREA AND BACK ELEVATION ELECTRICAL CONDUIT ROUTED THROUGH ROOF DRAIN SCUPPER CAUSING WATER TO POTENTIALLY COME IN CONTACT WITH ENERGIZED WIRES CAUSING A POTENTIAL ELECTRICAL HAZARD.

# FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15101733

CASE ADDR: 1216 CHATEAU PARK DR

OWNER: S R SINGH ENTERPRISES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERATIONS BY ENCLOSING THE GARAGE OF THE STRUCTURE.

### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES INCLUDING WATER HEATER.

### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL FIXTURES, SWITCHES AND OULETS.
- 2. CIRCUITRY FOR WATER HEATER.

### FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS WILL REQUIRE PERMITTING.

#### FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

\_\_\_\_\_\_

CASE NO: CE15092046
CASE ADDR: 2888 SW 19 PL
OWNER: CHULA VISTA LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED, MODIFIED AND/OR REMOVED PRIOR TO OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

- 1. THE REPLACEMENT OF THE EVAPORATOR UNIT, THERMOSTAT, THE CONDENSER UNIT, ALL REGISTERS AND ELECTRICAL CIRCUITS.
- 2. INSTALLED NEW A/C UNIT WITHOUT OBTAINING THE REOUIRED PERMITS.

# FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. COMMENCING ELECTRICAL ALTERATIONS AND MODIFICATIONS PRIOR TO OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, WALL OUTLETS, SWITCHES, AC SUPPLY TO ACCOMDATE AN ILLEGAL CONVERSION OF AN ADDITIONAL RENTAL UNIT.

### FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15111767
CASE ADDR: 2801 NE 38 ST
OWNER: DEZONIA, SHERRY K

SHERRY K DEZONIA 2008 TR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.8

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. BUILT 3 CANOPIES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15120410 CASE ADDR: 824 NE 20 AV

OWNER: HG MIDDLE RIVER INVESTMENTS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS RENOVATIONS, PAVERS AND FENCE INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS AND MINI SPLIT A/C SYSTEMS INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16010588

CASE ADDR: 3530 N FEDERAL HWY OWNER: ODABACHIAN, EDWARD

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE WITHOUT
THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15092254
CASE ADDR: 1214 NE 5 TER
OWNER: CARNES, RICK H

FILLERS, MARK W

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A FULL KITCHEN AND BATHROOM REMODEL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

# FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING FIXTURES BEING REMOVED AND REPLACED IN THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

# FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL DEVICES BEING REMOVED, REPLACED, OR ALTERED IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15102069

CASE ADDR: 1220 NE 3 ST # 103

OWNER: SWEENEY, THOMAS A & GLORIA &

SWEENEY, MICHAEL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. AN INTERIOR REMODEL AND REMODELING OF THE BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING BEING ALTERED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL BEING ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC (2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15110535

CASE ADDR: 6201 N FEDERAL HWY

OWNER: PLAZA 6201 LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF LOW VOLTAGE
LIGHTING, CAMERAS AND ELECTRICAL SIGNAGE AROUND
THE STOREFRONT WINDOWS AND DOORS WHICH WERE
INSTALLED WITHOUT THE REQUIRED LOW VOLTAGE
ELECTRICAL PERMIT AND/OR INSPECTIONS.

2. THE ELECTRICAL PANEL HAS BEEN ALTERED WITH ELECTRICAL MODIFICATIONS WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15120949
CASE ADDR: 1122 NE 1 AV
OWNER: H.O.M.E.S INC
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE WITH A KITCHEN
AND BATHROOM REMODEL INCLUDING REMOVING AND
REPLACING THE TILE BACKING BOARD AND INSTALLING A
FRENCH DOOR UNIT WITHOUT THE REQUIRED PERMITS AND/
OR INSPECTIONS.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

#### FBC (2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE TO THE KITCHEN AND BATHROOM, REMOVING AND REPLACING THE PLUMBING FIXTURES AND INSTALLING A TANKLESS WATER HEATER WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE TO
THE KITCHEN AND BATHROOM REMOVING AND REPLACING
ELECTRICAL DEVICES WITHOUT THE REQUIRED ELECTRICAL
PERMIT AND/OR INSPECTIONS.

\_\_\_\_\_\_

CASE NO: CE16011103

CASE ADDR: 2624 NE 30 PL # 103B OWNER: WILLIAMS, ASHLEY DAWN

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. RENOVATIONS AND WORK BEING DONE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

# FBC(2014) 105.3.1.4.11

THIS CONDO BUILDING/UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. HAVING MECHANICAL ALTERATIONS MADE WHERE A/C UNITS HAVE BEEN INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED AND/OR ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16011959

CASE ADDR: 2941 E LAS OLAS BLVD OWNER: ILENE RICHMOND LIV TR

LORRAINE VREELAND REV LIV TR ETAL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS DEMOLITION, FRAMING AND DRYWALL WORK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING DEMOLITION AND/OR ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS SUCH AS LOW VOLTAGE LIGHTING, CAMERAS, OUTLETS INSTALLED OR ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

### FBC (2014) 111.1.1

THIS PROPERTY HAS BEEN ALTERED WHERE THE PREVIOUS BUSINESS WAS ISSUED A CERTIFICATE OF OCCUPANCY FOR OPERATING AS A RESTAURANT UNDER AN ASSEMBLY USAGE CLASSIFICATION. THE BUSINESS CLASSIFICATION HAS NOW CHANGED TO A GROUP M MERCANTILE OCCUPANCY WITHOUT FIRST RECEIVING THE REQUIRED CHANGE OF USE AND ISSUED A NEW CERTIFICATE OF OCCUPANCY.

CASE NO: CE16020467

CASE ADDR: 2880 NE 32 ST #4

OWNER: KAZES, SHIMON

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES ALTERATIONS MADE SUCH AS FRAMING AND TILE BACKING BOARD/DRYWALL INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES ELECTRICAL ALTERATIONS AND REMOVING AND REPLACING THE ELECTRICAL PANEL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

# FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16020724

CASE ADDR: 1700 E LAS OLAS BLVD OWNER: VIGLIONE PROPERTIES LP

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE INSTALLING STEEL PLATES THAT ARE BOLTED INTO THE CONCRETE COLUMNS AND INSTALLING AND WELDING STEEL BEAMS IN PLACE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE AND POTENTIAL LIABILITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16020922

CASE ADDR: 2181 NE 67 ST # 611 OWNER: RABAH, INNA BILOUS

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE COMPLETE DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE DEMO OF THE KITCHEN AND BATHROOM PLUMBING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE DEMOLITION OF THE KITCHEN AND BATHROOM ELECTRICAL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ALTERATION OF THE MECHANICAL VENTILATION FOR THE KITCHEN WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

### FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE16021331

CASE ADDR: 1881 MIDDLE RIVER DR # 502

OWNER: LEVEQUE, GAYLE

LEVEQUE, PATRICK

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE COMPLETE REMODEL OF THE KITCHEN, BATHROOMS WITH ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, WINDOWS REPLACED, DROPPED CEILING IN KITCHEN WITH ELECTRICAL AND COMPROMISED THE FIREWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH PLUMBING ALTERATION MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH ROMEX WIRING, BLUE CUT IN BOXES, THE KITCHEN LAYOUT HAS BEEN ALTERED AND NOW THE REFRIGERATOR IS BLOCKING THE ELECTRICAL PANEL AND OTHER ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.11

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL EXHAUST FANS BEING REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING CONDO UNITS AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

### FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE16021361

CASE ADDR: 5321 NE 24 TER # 107A

OWNER: NICOLAZZO, ELIZABETH & DOMINGO

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE COMPLETE REMODEL OF THE KITCHEN AND BATHROOMS WITH REMOVING AND REPLACING THE TILE BACKING BOARD WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH PLUMBING ALTERATION MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.
- 2. A TANKLESS WATER HEATER HAS ALSO BEEN INSTALLED WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO THE KITCHEN AND BATHROOMS BEING REMODELED WITH ROMEX WIRING, BLUE CUT IN BOXES, AND THE ELECTRICAL PANEL REPLACED AND OTHER ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

# FBC(2014) 105.3.1.4.11

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL EXHAUST FANS BEING REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

# FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING CONDO UNITS AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_

CASE NO: CE16030002

CASE ADDR: 2933 POINSETTIA ST

OWNER: CORTEZ PROPERTY DEV LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. A FENCE INSTALLED AROUND THE PERIMETER OF THIS PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15010557
CASE ADDR: 1521 NW 8 AVE
OWNER: 1519 NW 8 AVE LLC

INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC 105.1

- 1. THE EXTERIOR WALL BEHIND THE A/C COMPRESSORS HAS BEEN ALTERED WITHOUT PERMITS CREATING AN UNSAFE CONDITION.
- 2. AT LEAST 1 OF THE KITCHENS HAS HAD THE CABINETS REPLACED WITHOUT A PLUMBING OR ELECTRICAL PERMIT.
- 3. THE WATER HEATER HAS BEEN REPLACED.
- 4. AT LEAST ONE BATHROOM SINK HAS BEEN REPLACED. ADDITIONAL VIOLATIONS MAY EXIST.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINNING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A/C COMPRESSOR.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

.-----

CASE NO: CE15121424
CASE ADDR: 1020 NW 5 CT
OWNER: 716 S W LLC
INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC(2014) 105.1

I RECEIVED A CALL REGARDING A FENCE BEING

INSTALLED WITHOUT PERMIT ON 12/16/15. I DID A SITE VISIT ON 12/17/15, POSTED A STOP WORK ORDER AND

TOOK PICTURES.

1. A CHAIN LINK FENCE WAS BEING INSTALLED AND COMPLETED

EXCEPT FOR THE GATE THAT WAS ON SITE BUT NOT

INSTALLED.

\_\_\_\_\_\_

CASE NO: CE15121428
CASE ADDR: 1425 NW 24 AV

OWNER: GORDON, EDWARD E &

HARBIN, MARY A

INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC(2014) 105.1

I RECEIVED A CALL ON 12/16/15 ABOUT A FENCE BEING INSTALLED WITHOUT PERMIT. I DID A SITE VISIT ON 12/17/15, POSTED STOP WORK ORDER AND TOOK PICTURES.

1. A WOOD FENCE WAS IN THE PROSESS OF BEING INSTALLED.

NO PERMIT COULD BE FOUND IN RECORDS.

-----

CASE NO: CE15101042 CASE ADDR: 1815 SW 4 ST

OWNER: TRUESDALE, ANDREW INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC (2014) 105.1

INSPECTOR RALPH RILES REPORTED TO ME THAT DURNING AN INSPECTION FOR REROOF AT THIS LOCATION FOR RENEWED PERMIT 06023197, HE FOUND WHAT APPEARED TO BE A SMALL ADDITION BUILT WITHOUT PERMIT. AFTER A REVIEW OF THE PERMIT HISTORY, PHOTOS FROM BCPA'S WEB SITE AND A SITE VISIT, I HAVE DETERMEND THIS

STRUCTURE WAS BUILT WITHOUT PERMITS. THE WORK INCLUDES

ELECTRICAL AND PLUMBING WORK.

FBC(2014) 110.6

APPROVAL REQUIRED. NO WORK SHALL BE DONE ON ANY PART OF A BUILDING OR STRUCTURE OR ANY, ELECTRICAL, MECHANICAL OR PLUMBING INSTALLATION BEYOND THE POINT INDICATED HEREIN ABOVE FOR EACH SUCCESSIVE INSPECTION UNTIL SUCH INSPECTION HAS BEEN MADE AND THE WORK APPROVED AND THE INSPECTOR HAS SO INDICATED ON THE PERMIT CARD OR AN

INSPECTION RECORD PAD AT THE JOB SITE WHICH HAS

BEEN APPROVED BY THE BUILDING OFFICIAL.

\_\_\_\_\_\_

CASE NO: CE15101989
CASE ADDR: 1724 SW 30 PL
OWNER: REICH, DAVID W
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNERS DRAWINGS WITH THE WIND PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC (2014) 2224.1 FOR CH/LK AND FBC (2014) 2328.1 FOR WOOD FENCE THAT WAS ERECTED OVER 6 FFET IN HEIGHT. IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED AT THAT LOCATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102260
CASE ADDR: 1312 NW 15 ST
OWNER: WILCOX, ALICIA
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WIND PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CH/LK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK

WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT

LOCATION.

1. A WOOD FENCE WAS ERECTED ON THE PROPERTY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15102342
CASE ADDR: 1761 NW 26 TER

OWNER: AVIMAR TR

MARAVI LLC TRSTEE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNERS DRAWINGS WITH THE WIND PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CH/LK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK

WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT

LOCATION.

1. A WOOD FENCE WAS ERECTED AROUND THE PROPERTY LOT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102378

CASE ADDR: 680 TENNIS CLUB DR # 301

OWNER: LOPEZ, DENNIS R

LOPEZ, DENNIS A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. WORK WITHOUT PERMIT IN PROGRESS. THE INTERIOR OF THE UNIT WAS GUTTED WITHOUT A DEMO PERMIT.
- 2. RENOVATIONS ARE BEING DONE AS FRAMING, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE PROPER PERMITS AND INSPECTIONS, INCLUDING THE OPENINGS ON THE FIRE PARTITONS.
- 3. WINDOWS WERE REPLACED.
- 4. CENTRAL A/C IS BEING REPLACED AND THE DUCT WORK IS BEING ALTERED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15102497
CASE ADDR: 1213 NW 14 ST
OWNER: MOONEY, CHRISTINA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WIND PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CH/LK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST BE

WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT

LOCATION.

1. A WOOD FENCE WAS ERECTED WITHOUT THE REQUIRED PERMITS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15110196 CASE ADDR: 1701 NW 14 CT

OWNER: 2771 LLC INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WIND PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CH/LK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK

WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT

LOCATION.

1. A WOOD FENCE WAS ERECTED AT THE PROPERTY

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

-----

RETURN HEARING (OLD BUSINESS)

\_\_\_\_\_\_

CASE NO: CE13091177 CASE ADDR: 3210 NW 63 ST

OWNER: STYCZYNSKY, RANDALL W

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

1. REPLACING WINDOWS AND DOORS.

2. ALTERING OPENING FROM WINDOWS TO DOORS, WHICH INCLUDES FILLED CELLS AND ELECTRICAL WORK.

ALL WORK DONE WITHOUT THE REQUIRED PERMITS OR

INSPECTIONS.

FBC(2010) 105.4.15

REPLACING WINDOWS AND DOORS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ADDING ELECTRICAL WIRING, ELECTRICAL BOXES, AND FUTURE FIXTURES WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 1604.1

ALTERING EXTERIOR OPENINGS FOR BOTH WINDOWS AND DOORS THAT INCLUDES FILLED CELLS, BLOCK, POURED SILLS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

\_\_\_\_\_\_

CASE NO: CE14040754
CASE ADDR: 91 COMPASS LA

OWNER: BRESLOW, JULIAN MARIE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 116.2.1.2.1

PART OF THE SEAWALL HAS BEEN DAMAGED AND NEEDS TO

BE REPAIRED.

-----

CASE NO: CE14070536

CASE ADDR: 200 S BIRCH RD # 1109

OWNER: TRIMPE, JANET INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE KITCHEN RENOVATION WHICH INCLUDES STRUCTURAL WORK INCLUDING FRAMING AND DRYWALL. WORK PERFORMED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

### FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE KITCHEN REMODEL WHICH INCLUDES REMOVING AND REPLACING THE PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 105.4.5

- 1. THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE KITCHEN REMODEL WHICH INCLUDES REMOVING AND REPLACING ELECTRICAL DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.
- 2. THE ELECTRICAL PANEL HAS ALSO BEEN REPLACED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

### FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE ADDR: 1311 SEMINOLE DR OWNER: DANIELSSON, LEIF INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY IS BEING ALTERED WITH THE FOLLOWING WORK BEING DONE WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT

LIMITED TO:

1. EXTERIOR WALL REPAIR.

NEW DOCK.
 NEW TIKI HUT.

4. WHAT APPEARS TO BE POST FOR A FENCE OR TRELLIS.

5. REMOVING AND REPLACING A PAVER DECK.

CASE NO: CE14110327
CASE ADDR: 433 NE 14 AVE
OWNER: BROOKS, SCOTT

NEW OWNER: ALEXANDRA SANTIBANEZ IRREV TR

SANTIBANEZ, ONEY TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14111609

CASE ADDR: 545 S FTL BEACH BLVD 1101

OWNER: WISMER, GERALD BRUCE
NEW OWNER: BRENNAN, MICHAEL
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC (2010) 105.4.3

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION OF THE FRAMING AND DRYWALL THROUGHOUT THE KITCHEN, BATHROOMS, AND OTHER AREAS OF THIS UNIT WITHOUT THE REQUIRED DEMOLITION PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE ALTERATION OF ELECTRICAL WIRING AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT ALL REQUIRED PERMITS ARE OBTAINED, INSPECTED, PASSED AND CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE IN THIS CONDO BUILDING.

\_\_\_\_\_

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15011944
CASE ADDR: 609 NE 8 AV

OWNER: ELITE HOME PARTNERS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR AND EXTERIOR RENOVATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE FRONT DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

.\_\_\_\_\_

CASE NO: CE15041506 CASE ADDR: 928 NE 20 AVE

OWNER: NE 20 AVE PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH A CANOPY AWNING INSTALLED WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH A CANOPY AWNING INSTALLED THAT HAS ELECTRICAL INSTALLED THROUGHOUT WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15041877

CASE ADDR: 4300 N OCEAN BLVD # 17J

OWNER: HOLOTKA, JOANNE M INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR

REMODEL WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15051433 CASE ADDR: 1728 NE 20 AVE

OWNER: CARL A HOLCOMB REV LIV TR

HOLCOMB, CARL A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. A/C UNITS WERE INSTALLED.
- 2. KITCHEN CABINETS ARE BEING REPLACED WHICH REQUIRE PLUMBING PERMIT FOR SINK INSTALLATION AND ELECTRICAL PERMIT FOR GFI ON THE COUNTER.

#### FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLATION OF DUCTLESS A/C UNITS.

### FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. SINK INSTALLATION FOR KITCHEN CABINETS.

#### FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL GFI FOR KITCHEN CABINETS AND ELECTRICAL FOR A/C UNITS.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15071130

CASE ADDR: 117 S GORDON RD
OWNER: LAURENT, REGINALD
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.1

THE DOCK AT THE REAR OF THE PROPERTY WAS

REFINISHED WITH AN APPLIED PERMIT# 15060297. TODAY

IT HAS BECOME WORK WITHOUT A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15080318

CASE ADDR: 4040 GALT OCEAN DR # 619

OWNER: WENKING LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL, REFINISHING, ALTERATION, AND REPLACEMENT OF THIS FRONT ENTRY DOOR WITHOUT THE REQUIRED PERMIT AND OR INSPECTIONS. THIS DOOR IS NOT A FIRE RATED DOOR. THIS ISSUE WAS ALSO ADDRESSED BY THE

F.L.F.D.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE AN A.T.F. PERMIT BE OBTAINED AND DOUBLE FEES WILL APPLY.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND DOUBLE PERMIT FEES WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS

FULLY COMPLIED AND CLOSED.

CASE NO: CE15082281

CASE ADDR: 2400 E OAKLAND PARK BLVD

OWNER: SP4 INVESTMENTS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

- 1. A ROOM CONVERTED INTO A SHOWER.
- 2. A ROOM ALTERED INTO A KITCHENETTE WITH A WASHER AND DRYER. THIS WORK INCLUDES FRAMING AND DRYWALL WORK DONE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.11

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. MECHANICAL WORK INSTALLED FOR THE INSTALLATION OF A DRYER WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.4

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. PLUMBING WORK INSTALLED TO INCLUDE A NEW SHOWER, A WASHER MACHINE, AND A TANKLESS WATER HEATER INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK INSTALLED TO INCLUDE ELECTRICAL FOR A WASHER AND DRYER, ELECTRICAL SUB PANEL INSTALLED UNDER THE KITCHENETTE SINK FOR A TANKLESS WATER HEATER AND POSSIBLY OTHER APPLIANCES. THERE ARE MISCELLANEOUS ELECTRICAL REPAIRS OR ALTERATIONS THAT HAVE BEEN MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC (2014) 107.1.1

BECAUSE OF THE SEVERITY AND COMPLEXITY OF THIS CODE CASE AND THE ALTERATIONS THAT HAVE BEEN MADE TO THIS COMMERCIAL SPACE, THIS CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL. THESE DRAWINGS NEED TO DOCUMENT THE VIOLATIONS THAT EXIST AND THE METHOD AND CORRECTIONS THAT NEED TO BE MADE TO CORRECT ALL OF THE VIOLATIONS THAT EXIST IN THIS COMMERCIAL SPACE.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

.\_\_\_\_\_

CASE NO: CE15101589

CASE ADDR: 3200 NE 36 ST # 411 OWNER: BAUCO, DOMENICO

BAUCO, MARISA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES BUT IS NOT

LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.2

A PRELIMINARY INSPECTION WILL BE REQUIRED BEFORE THE AFTER THE FACT PLAN REVIEW IS APPROVED.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

-----

CASE NO: CE15102449

CASE ADDR: 2500 LUCILLE DR
OWNER: KLAIRMONT, LARRY
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO THE INSTALLATION OF THE FOLLOWING ITEMS WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS:

- 1. THE ENTIRE DOCK HAS BEEN REFACED AND PART OF THE SUB FRAMING JOIST OR STRINGERS HAS BEEN REPLACED.
- 2. THERE ARE TWO BOAT LIFTS INSTALLED. A WAVE RUNNER RAMP INSTALLED WITH POLE PILINGS AND ANCHORS TO THE SEAWALL, AND TWO SMALL BOAT DAVITS ANCHORED ON THE SEAWALL/DOCK AREA. THERE ARE NO PERMIT RECORDS FOR THIS WORK INSTALLED.

### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE INSTALLATION OF ELECTRICAL CONDUIT, WIRING, BOXES, AND FIXTURES THROUGHOUT THIS ENTIRE DOCK AND THE PILINGS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING

CODE.

#### FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

### FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

#### FBC(2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

\_\_\_\_\_\_

CASE NO: CE16010199
CASE ADDR: 2811 NE 56 CT
OWNER: LACHO & FRANZ LLC
INSPECTOR: ROBERT MASULA

### VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERING THE SEAWALL CAP.
- 2. ALTERING EXTERIOR OPENINGS ON THE HOUSE.
- 3. PATIO ENCLOSURE.
- 4. INTERIOR RENOVATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

#### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING THE MECHANICAL SYSTEM WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING ELECTRICAL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY, AND POTENTIAL LIABILITY OF THE VIOLATIONS FOR THIS PROPERTY, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

#### FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

### FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. PLUMBING ALTERATION MADE:
- A. REMODELING KITCHENS, BATHROOMS, REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE:
- A. ELECTRICAL PANELS REPLACED, DISCONNECTS INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

### FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

### FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

\_\_\_\_\_\_

CASE NO: CE14051440 CASE ADDR: 1663 NW 15 TER OWNER: ALLADIN, VANEL INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE DWELLING'S OPENINGS WERE BOARDED AND THE WOOD HAS BEEN REMOVED.

- 2. NEW WINDOWS AND EXTERIOR DOORS WERE INSTALLED ON THEM.
- 3. INTERIOR UPGRADE INSIDE THE KITCHEN AND BATHROOMS AREAS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15051147 CASE ADDR: 2170 NW 29 TER OWNER: SWINTON, LORENZO V INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE EXISTING CENTRAL A/C UNIT THAT WAS INSTALLED WITH A BROWARD COUNTY PERMIT HANGING FROM THE DWELLINGS GABLE HAS BEEN REPLACED WITHOUT A PERMIT AND RELOCATED TO THE GROUND WITH NEW DUCT WORK AND ELECTRICAL SERVICE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15051584 CASE ADDR: 1621 NE 20 AV OWNER: PIEKARSKI, JASON INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. THERE IS A CURRENT PERMIT# 15042829, FOR DOOR AND WINDOW REPLACEMENTS. IT APPEARS THAT THEY ARE WORKING BEYOND THE SCOPE OF THE ISSUED PERMIT AS THE BATHROOM AND KITCHEN HAVE RENOVATIONS IN PROGRESS.

2. WATER HEATER HAS BEEN REMOVED FROM ITS APPROVED LOCATION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT

THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15051950 CASE ADDR: 6520 NE 21 AV PETERS, WILLIAM A DAVIDSON, WARREN

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. REPLACEMENT OF AIR CONDITIONING UNIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE

PERMITTING PROCESS.

CASE NO: CE15080754
CASE ADDR: 1706 NW 14 CT
OWNER: TUCHOW, TYLER
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. GARAGE WAS CONVERTED INTO LIVING SPACE.

CONSTRUCTION OF A SECOND BATHROOM.
 AIR CONDITIONING SYSTEM CHANGE OUT.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

------

CASE NO: CE15090341
CASE ADDR: 3680 SW 16 ST
OWNER: RHA 2 LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WATER HEATER REPLACEMENT

2. ADDITION OR ALTERATION OF WATER AND ELECTRICAL CONNECTIONS FOR WATER HEATER, WASHER AND DRYER.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14060442
CASE ADDR: 727 NW 17 ST
OWNER: DALL 2 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND CERTIFICATE OF OCCUPANCY

FROM THE CITY BUILDING DEPARTMENT:

THIS CASE WAS OPENED TO ADDRESS THE ORIGINAL COMPLAINT CE12040793 FOR WORK WITHOUT PERMITS AND A STOP WORK ORDER WAS ISSUED BACK THEN.

- 1. SOME MAJOR RENOVATIONS WERE DONE, OTHERS WERE IN-PROGRESS WITHOUT PERMITS. THIS INCLUDES THE REMOVAL AND CONSTRUCTION OF INTERIOR WALLS AND ALTERATIONS OF THE APPROVED FLOOR PLAN OF THE DWELLING.
- 2. THE EXISTING BATHROOMS AND KITCHEN WERE ENTIRELY ALTERED WITH ELECTRICAL AND PLUMBING FIXTURES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15061757
CASE ADDR: 4010 BAYVIEW DR

OWNER: KOFFMAN, TRACY & KEVIN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. INSTALLED BOAT LIFT WITH AN ELECTRICAL 220V. RUN WITHOUT PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING AND INSPECTION PROCESS.

CASE NO: CE14050728 CASE ADDR: 2840 NE 25 ST

OWNER: CLEMENTE, DANIELA VALENTI

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT DOCK.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE14071684
CASE ADDR: 1608 SW 10 CT
OWNER: SOFREI LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. INTERIOR ALTERATIONS OF THE ELECTRICAL, PLUMBING AND MECHANICAL SYSTEMS.
- 2. DRYWALL REPLACEMENT INSIDE THE KITCHEN AND BATHROOMS AREAS.
- 3. THE WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 4. THE PROPERTY WAS RE-ROOFED WITH SHINGLES. THE PERMIT WAS LEFT TO EXPIRE WITHOUT PASSING FINAL INSPECTIONS. TODAY IT REMAINS WORK WITHOUT PERMITS.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110272 CASE NO: CE15010862

CASE ADDR: 2679 MARATHON LN
OWNER: DA ROSA, JOSE SIMOES

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CARPORT AND PORTIONS OF THE BUILDING HAVE BEEN CLOSED IN, INCLUDING WINDOWS AND DOORS.

### FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOM INSIDE THE ENCLOSED SECTION OF THE CARPORT.

#### FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLY CLOSED IN PORTIONS OF THE BUILDING.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15041915
CASE ADDR: 1309 NW 15 CT
OWNER: DALL 2 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. ILLEGAL CONVERSION OF THE OPEN CARPORT INTO 1/1 RENTAL APARTMENT WITH AN EXTRA COOKING AREA AND A BATHROOM.
- 2. THE ELECTRICAL AND PLUMBING SYSTEM WAS ALTERED TO BUILD THE APARTMENT IN THE OPEN CARPORT THAT WAS ENCLOSED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15042161
CASE ADDR: 2505 NW 20 ST
OWNER: IRVIN, DOROTHY H

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONSTRUCTION HAS CONTINUED WITH EXPIRED PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15051829
CASE ADDR: 1804 NW 16 CT
OWNER: TUCHOW, TYLER
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE CARPORT HAS BEEN ENCLOSED.
- 2. PLUMBING, ELECTRICAL & MECHANICAL WORK HAVE BEEN DONE WITHIN THE ENCLOSED CARPORT FOR A BATHROOM AND WASHER AND DRYER.

### FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLYING THE ENCLOSED CARPORT.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2010) 111.1.1

USE AND OCCUPANCY. NO BUILDING OR STRUCTURE SHALL BE USED OR OCCUPIED, AND NO CHANGE IN THE EXISTING OCCUPANCY CLASSIFICATION OF A BUILDING OR STRUCTURE OR NATURE OR USE OR PORTION THEREOF SHALL BE MADE UNTIL THE BUILDING OFFICIAL HAS ISSUED A CERTIFICATE OF OCCUPANCY THERE FOR AS PROVIDED HEREIN. SAID CERTIFICATE SHALL NOT BE ISSUED UNTIL ALL REQUIRED ELECTRICAL, GAS, MECHANICAL, PLUMBING AND FIRE PROTECTION SYSTEMS, AND PROVISIONS OF FFPC HAVE BEEN INSPECTED FOR COMPLIANCE WITH THE TECHNICAL CODES AND OTHER APPLICABLE LAWS AND ORDINANCES AND RELEASED BY THE BUILDING OFFICIAL. ISSUANCE OF A CERTIFICATE OF OCCUPANCY SHALL NOT BE CONSTRUED AS AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION.

CASE NO: CE15061690
CASE ADDR: 3341 NE 42 CT
OWNER: BIELEN, ARVIN N

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILDING STRUCTURES IN BACKYARD AND/OR BACK OF PROPERTY WITHOUT OBTAINING BUILDING PERMITS AS REQUIRED BY THE FLORIDA BUILDING CODE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE15070786

CASE ADDR: 1437 NE 56 ST

OWNER: BRODETZKI, YUVAL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT A PERMIT. IT HAS BEEN CONVERTED TO FIVE UNITS. APPROVED USE IS FOR A SINGLE UNIT FAMILY RESIDENCE.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

WINDOW AND DOOR INSTALLATIONS AND ALTERATIONS WITHOUT A PERMIT

FBC(2014) 105.3.1.4.4

THE PLUMBING HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.4.1.2

OWNER OF RECORD IS RESPONSIBLE TO ABIDE BY FLORIDA BUILDING CODE AS OUTLINED IN FLORIDA STATUTES.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 111.4.1

PROPERTY IS A SINGLE FAMILY RESIDENCE APPROVED FOR SINGLE USE. THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A FIVEPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

\_\_\_\_\_\_

CASE NO: CE15070923 CASE ADDR: 216 ROSE DR

OWNER: CECERE, LEONARD & MARY M

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED CANOPY AND ANCHORED TO BUILDING WITHOUT A PERMIT.

#### FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT AND CONVERTED INTO GARAGE WITHOUT A PERMIT.

### FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AT CARPORT ALTERATION WITHOUT A PERMIT.

### FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED GARAGE DOOR TO CONVERTED CARPORT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_

CASE NO: CE15080572 CASE ADDR: 1201 NE 5 AV

OWNER: EM INVESTMENT REV TR

MILITZOK & LEVY PA TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED A FIFTH UNIT TO A FOURPLEX, ALTERED THE CONFIGURATION OF THE WALLS, THE ELECTRICAL, MECHANICAL AND PLUMBING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A FOUR UNITS TO FIVE UNITS WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2014) 111.4.1

UNIT OCCUPIED IN VIOLATION OF THIS CODE MUST BE VACATED.

-----

CASE NO: CE15081055
CASE ADDR: 1208 NW 19 AV
OWNER: GREEN, LINDA
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED To:

- 1. INTERIOR REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS.
- 2. BUILDING A SHED IN THE BACKYARD WITHOUT OBTAINING THE REQUIRED PERMITS.

#### FBC(2014) 105.3.1.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING AN AIR CONDITIONING CONDENSER UNIT WITHOUT OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.4.4

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING AN IRRIGATION SYSTEM WITH WELL PUMP AND TIMER WITHOUT OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC(2014) 105.3.1.4.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING ELECTRICAL FOR IRRIGATION SYSTEM WITH WELL PUMP AND TIMER WITHOUT OBTAINING THE REQUIRED PERMITS.

CASE NO: CE15081297
CASE ADDR: 3051 NW 23 ST
OWNER: WILLIAMS, THERESA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 116.1.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. STRUCTURE BUILT AT EDGE OF POOL WITHIN THE REQUIRED 5 FOOT SETBACK WITHOUT OBTAINING THE REQUIRED PERMITS. POOL NOT DESIGNED TO SUPPORT THE WEIGHT OF THE ILLEGAL STRUCTURE.

#### FBC(2014) 116.2.1.2.4

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. THE ROOF IS SAGGING AND HAS THE POTENTIAL FOR FAILURE.

### FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT AN ADDITION WITHOUT A PERMIT WHICH IS DEEMED UNSAFE AND IS STRUCTURALLY FAILING.

#### FBC(2014) 105.3.1.4.5

ELECTRICAL SYSTEM ALTERED TO INCORPORATE ILLEGAL ADDITION WITHOUT OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.4.11

AIR CONDITIONING INSTALLED AND ALTERED TO INCORPORATE ILLEGAL ADDITION WITHOUT OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.4.15

INSTALLATION OF DOOR WITHOUT OBTAINING THE REQUIRED PERMITS.

### FBC(2014) 105.3.1.5

DESIGN AND ENGINEERING DOCUMENTS NOT SUBMITTED TO OBTAIN PERMIT APPROVAL.

CASE NO: CE15082095
CASE ADDR: 2308 NW 26 ST
OWNER: WALKER, MAURICE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INSTALLATION OF DOORS WITHOUT THE REQUIRED PERMIT.
- 2. REBUILDING OF THE EXTERIOR PORCH CEILING, INCLUDING WIRE LATH, WITHOUT THE REQUIRED PERMIT.

#### FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT AN ADDITION IN THE BACK WITHOUT THE REQUIRED PERMIT.

### FBC(2014) 105.3.1.4.4

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED AN IRRIGATION SYSTEM WITHOUT OBTAINING THE REQUIRED PERMIT.

### FBC(2014) 105.3.1.4.10

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. RE-ROOFING WITHOUT THE REQUIRED PERMIT.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15082171 CASE ADDR: 2841 SW 9 ST

OWNER: VERNEUS, ALPHONSINE H/E

GASTON, IBRAM

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEN CONVERTED TO AN EFFICIENCY APARTMENT WITH A BATHROOM.

### FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A BATHROOM IN THE DEN WITHOUT ACQUIRING THE REQUIRED PERMITS.

#### FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED THE ELECTRICAL SYSTEM IN THE COVERTED DEN TO EFFICIENCY WITHOUT A PERMIT.

#### FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO

1. INSTALLED A CENTRAL A/C CONDENSOR UNIT WITHOUT THE REOUIRED PERMIT.

### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. CONVERTED DEN TO AN EFFICIENCY.

### FBC(2014) 116.2.1.2.5

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

FIRE DAMAGE IN THE BUILDING IS A POTENTIAL LIFE AND SAFETY HAZARD SINCE THE BUILDING IS STILL ENERGIZED AND OCCUPIED.

------

CASE NO: CE15090899 CASE ADDR: 1425 SW 10 ST

OWNER: 2015-3 IH2 BORROWER LP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT WITHOUT OBTAINING THE REQUIRED PERMIT.

### FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOW AT CARPORT ENCLOSURE WITHOUT THE REQUIRED PERMIT.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

-----

CASE NO: CE15092059
CASE ADDR: 1544 NW 9 AVE
OWNER: KDE OF FL 1 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY HOME TO A DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

#### FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS TO THE STRUCTURE. WINDOWS, DOORS, WALLS, BATHROOMS REMODEL, KITCHEN REMODEL, PLUMBING.

#### FBC(2014) 105.19.2

THE BUILDING OFFICIAL AT HIS/HER DISCRETION SHALL INTERPRET THE BUILDING CODE AND COMPLIANCE REQUIREMENTS.

#### FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURAL MODIFICATIONS OF INTERIOR WALLS.

#### FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF DOORS AND WINDOWS.

#### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. BATHROOM REMODEL WITH PLUMBING ALTERATIONS.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

FBC(2014) 105.4.1.2 OWNER RESPONSIBILITY.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS TO BE DOUBLE FEE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS.

FBC(2014) 116.1.2

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. PER FLORIDA BUILDING CODE WORK WITHOUT PERMIT IS DEEMED TO BE UNSAFE.

-----

CASE NO: CE15121199

CASE ADDR: 1251 E SUNRISE BLVD
OWNER: ROSHNI INVESTMENTS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 1013.4

- 1. OPENING ON GUARDRAILS EXCEED THE MAXIMUM ALLOWABLE UNDER THE SECTIONS OF THIS CODE OF 4 INCHES.
- 2. THIS IS AN EXIGENT LIFE AND SAFETY HAZARD THAT IMMEDIATE ATTENTION IS REQUIRED TO MAKE SAFE.

FBC (2014) 110.6

THIS VIOLATION IS IN PROGRESS AND REQUIRES INSPECTIONS AND APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE MITIGATION AND PERMITTING PROCESS.

-----

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE08070448 CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN

DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE

STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED

WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.

- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

\_\_\_\_\_\_

CASE NO: CE14072166
CASE ADDR: 907 NW 12 TER
OWNER: HASAN, ABEER
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOW:

- 1. THE OUTSIDE WALLS WERE RE-STUCCOED.
- 2. ELECTRICAL WIRES ARE EXPOSED IN THE METER CAN.
- 3. THE BATHROOM WINDOW AND THE EXTERIOR DOOR WERE REPLACED.
- 4. INTERIOR ALTERATIONS ARE IN PROGRESS: DRYWALL, PLUMBING AND ELECTRICAL FIXTURES HAVE BEEN REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14072224
CASE ADDR: 3621 SW 22 ST
OWNER: MARTIN, IDANIA
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. THE OWNERS OF THIS PROPERTY HAVE REMOVED A CHAIN LINK FENCE BELONGING TO 3620 SW 21 CT AND REPLACED IT WITH A WOOD FENCE.
- 2. THEY BUILT A SHED TO HOUSE LARGE DOGS AND IS ATTACHED TO THE WOODEN FENCE.
- 3. BETWEEN 2007 AND 2008 A STORAGE SHED WAS INSTALLED.
- 4. BETWEEN 2011 AND 2012 A SLAB ON GRADE WAS DONE ON THE WESTSIDE OF THE PROPERTY LOT.
- 5. IN 2012, WOOD FENCES WITH GATES WERE ERECTED ON BOTH SIDES OF THE PROPERTY FRONT FACING SOUTH.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110356

CASE ADDR: 2612 BARBARA DR
OWNER: MONDANI, GLEN H/E
MONDANI, PENTELOPE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT.

STOP WORK ISSUED.
THERE IS WORK IN PROGRESS WITH EXPIRED PERMITS:

1. COMPLETED RENOVATION INSIDE OF THE DWELLING.

- 2. AN ELECTRICAL GENERATOR WITH GAS OR LP SUPPLIED TO IT WAS INSTALLED. THREE GAS SUPPLY LINES RAN TO THE INTERIOR OF THE HOUSE.
- 3. THE GARAGE WAS DEMOLISHED AND A SERVANT'S QUARTERS WAS BUILT WITH ELECTRICAL AND PLUMBING ALTERATIONS.
- 4. HURRICANE SHUTTERS WERE INSTALLED.
- 5. AN EXTERIOR DOOR WAS REPLACED.
- 6. ALTERATIONS TO THE FRONT PORCH.
- 7. PAVERS IN THE DRIVEWAY WERE DONE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15041070
CASE ADDR: 1333 NE 15 AVE
OWNER: SPORN, KENNETH F &
DIMARIA, MARCELLO

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT A PERMIT. THERE ARE ALSO LIFE SAFETY VIOLATIONS BECAUSE THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN

APPROVED.

1. ELECTRICAL PERMIT #04120155 (EPOOL/SPAR)
2. BUILDING PERMIT #04120152 (BPOOL/SPAR)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR OWNER: WSC BRICKELL LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE14120163
CASE ADDR: 5920 NE 21 RD
OWNER: SOUA, MOUEZ
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ENCLOSED CARPORT AND CONVERTED TO GARAGE.
- 2. REPLACED WINDOWS AND DOORS FRONT ELEVATION.
- 3. INSTALLED GARAGE DOOR.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15040158

CASE ADDR: 400 ISLE OF CAPRI

OWNER: KUIJPER, MARTIJN PETER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE FOUR EXISTING AIR CONDITIONERS HAVE BEEN MOVED INTO THE EASEMENT WHICH IS LESS THAN TWO FEET FROM THE PROPERTY LINE.
- 2. POOL PUMPS AND CLEANING EQUIPMENT HAVE BEEN MOVED AND INSTALLED ON THE SOUTH SIDE OF HIS YARD.
- 3. A POOL AND SPA HEATER HAVE BEEN MOVED AND INSTALLED ON THE SOUTH SIDE OF HIS YARD.
- 4. A NEW GAS GENERATOR WITH NEW GAS LINES HAS BEEN INSTALLED ON THE SOUTH SIDE OF THIS YARD.
- 5. AN OUTDOOR KITCHEN HAS NOW BEEN ERECTED NEAR THE ORIGINAL LOCATION OF THE FOUR AIR CONDITIONERS. THIS CONSISTS OF THE CONSTRUCTION OF A CONCRETE OUTDOOR WALL APPROXIMATELY 12FT LONG AND 8FT TALL.
- 6. A NEW GAS LINE WAS MADE FOR THE GAS GRILL.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15072462
CASE ADDR: 1119 NE 15 AVE
OWNER: 1119 PROGRESSO LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN/BATH REMODEL WITHOUT PERMIT.
- CONVERTED GARAGE INTO A BEDROOM AND/OR LIVING SPACE WITHOUT PERMIT.
- 3. REMOVED AND REPLACED FIXTURES.
- 4. ATF PERMITS THAT WERE APPLIED FOR WERE VOIDED AND/OR NOT ISSUED.

### FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

#### FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

### FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

#### FBC(2014) 110.2

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

#### FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15042036

CASE ADDR: 3209 NE 36 ST # 4B
OWNER: MIGA, PATRICIA ANN T &

MIGA, STEVEN J

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANER:

1. REAR PATIO ENCLOSURE INSTALLED.

FBC (2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE15050511 CASE ADDR: 1132 NW 5 CT

OWNER: MCCULLOUGH, JOHNNY

HALL, ODESSA

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. THIS SINGLE STORY DUPLEX HAS BEEN CONVERTED INTO A FOURPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING

DEPARTMENT.

CASE NO: CE15061198
CASE ADDR: 1616 SE 2 CT
OWNER: FINN, ZACHARY
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PAVERS INSTALLED ON DRIVEWAY AND SWALE AREA.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE14091251
CASE ADDR: 1736 SE 14 ST
OWNER: VERDUGO, CARLOS E
INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(b)

- 1. THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.
- 2. THE SEAWALL AT THIS PROPERTY IS IN NEED OF REPAIRS AND MAINTENANCE.

FBC(2010) 105.4.3

- 1. THIS PROPERTY HAS BEEN ALTERED WITH THE PARTIAL DEMOLITION OF A DOCK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.
- 2. THE WOODEN DOCK HAS NOT BEEN MAINTAINED AND HAS NOW DETERIORATED FROM THE ELEMENTS. THIS STRUCTURE HAS NOW BECOME A WINDSTORM HAZARD AND IS UNSAFE.

FBC(2010) 105.4.18

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

------

CASE NO: CE15050611 CASE ADDR: 1416 NE 6 ST

OWNER: 1416 NE 6TH STREET LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE GAS WATER HEATERS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES AND GAS WATER HEATERS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE ELECTRICAL PANELS, OUTLETS, SWITCHES AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091319 CASE ADDR: 307 NE 23 AV

OWNER: WALTER A CROWELL TR

CROWELL, WALTER A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF AN OUTDOOR KITCHEN

STRUCTURE BUILT WITHOUT THE REQUIRED PERMIT AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF A GAS LINE INSTALLED FOR AN OUTDOOR KITCHEN WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15102548

CASE ADDR: 200 S BIRCH RD # 209

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(B)

THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.

- 1. THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:
- A. THE ORIGINAL A/C WALL UNIT APPLIANCE HAS BEEN REMOVED ALONG WITH THE ORIGINAL APPLIANCE SHELVES THAT WAS ORIGINALLY ANCHORED INTO THE WALL OPENING. THE OPENINGS EITHER NEED TO BE PROPERLY CLOSED IN WITH A STRUCTURAL PERMIT SPECIFYING THE METHOD OF CONSTRUCTION TO BE USED. IF THE INTENTION IS TO REPLACE THESE A/C WALL APPLIANCE UNITS THEN A COMPLETE UNIT WITH THE STRUCTURAL ATTACHED SHELVES NEEDS TO BE PROPERLY INSTALLED AND ANCHORED INTO THE WALL OPENING. THIS WILL AT A MINIMUM REQUIRE A MECHANICAL PERMIT FOR REPLACING THE ENTIRE ASSEMBLY.

### FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING BEING ALTERED IN THE BATHROOM BY REMOVING AND REPLACING THE TOILET AND SINK WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTION.

### FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL PANEL BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.